
Southern Company Gas

Stop Work Authority (SWA) is a 5-step process

STOP | NOTIFY | DISCUSS | CORRECT | RESUME

Stop work immediately with the Safe T signal!



1. STOP

If you perceive condition(s) or behavior(s) that pose danger or risk, **stop work** and take a pause.

2. NOTIFY

Notify affected personnel and supervision of the **stop work** action.

3. DISCUSS

Personnel will discuss the situation and agree on the **stop work** action.

4. CORRECT

Personnel will agree on corrective actions to mitigate the risk.

5. RESUME

Notify affected personnel of corrective actions. Once the risk is mitigated, it is safe to resume work.

©2024 Southern Company Gas, All Rights Reserved. GAS-22721