Matter:	FCR-27	Orginal File:	J. Reynolds Testimony FCR-27-TS-FINAL
Docket No.	56765	Orginal File Dated:	8-Apr-26
Testimony of:	Joseph Reynolds	Date Filed:	9-Apr-26
Page	**Line**	**Correction**	**Reason**
15	16	It would be fundamentally unfair for ratepayers to absorb this cost given the poor performance of Company management and their Vendors.	"Venders" was capatilized in new version
19	17	Footnote 4, "Full shear of the suction line occurs when the small drain line breaks completely away from the larger feedwater supply line. See Figure 2 – Location of failure in 1” pipe stub between socket welded connections -Pg 6 of 134 NMP-GM-002-F09"	
22	14	Loss of this fuse then caused an automatic reactor trip due to excessive cooldown and rapid power reduction from a steady state of 100% power.	This sentence was added to the answer of the question.
23	15	Therefore, ratepayers should not be responsible for this unnecessary replacement fuel cost that is associated with the plant shutdown caused by a Vendor defective design.	Grammar and Punctuation
24	7	The company found foreign material inside of the positioner internal pressure regulator of the main feedwater control valve.	Further explanation
24	9	The Company determined from its records that the foreign material must have been introduced during its assembly by the manufacturer.	Changed the word "the" to "it's".

25	8	Therefore, it is my conclusion that it was imprudent for the Vendor manufacturer of the Feedwater Valve to allow foreign material to be contaminating the valve that caused its malfunction.	
25	18	Ultimately, temperature deviation rose to +10 degrees Fahrenheit, leading the operators to perform a manual trip of the reactor.	Grammar and Punctuation
26	11	"Yes, work practice during construction was less than adequate." Footnote 6 - "See Photograph of subject terminal block installation. Pg. 3 of 16, NMP-GM-002-F22"	Footnote 6 was added.
26	20	It is my conclusion that the installation Vendors were imprudent in the selection of the terminal component and installation of it's wiring, and that this outage is clearly a warranty item. Therefore, ratepayers should not be held responsible for paying the replacement fuel cost of this outage caused by Venders.	Grammar and Punctuation
28	-	Provided testimony at rate base hearings before state public service commissions involving the utility's handling of unplanned plant outages, and evaluation of the resulting repair costs.	Grammar and Punctuation - made "hearing" pluaral