

GEORGIA POWER COMPANY
Docket No. 29849
Staff Data Request No. STF-199

STF-199-2 (May 2021 Supplement)

Question:

The following questions concern the Unit 3 damaged blowdown line expansion joint. Consider this a standing data request until all work to rectify the remediation is complete and all Corrective Action Program documentation is complete.

- a. Please provide all CRs (full report) ESRs and all other CAP or engineering documents related to this damage;
- b. Please provide all analyses, root cause analyses or other documents that discuss the cause and/or corrective actions for this damage;
- c. Please provide all actions taken and documents related to the extent of condition related to this damage;
- d. Please describe all actions taken to protect similar expansion bellows following this event;
- e. Please describe the damage to the blowdown line expansion joint including how the damage was discovered, how the damage occurred if known and the action required to replace the expansion joint and return the blow;
- f. Please describe the action(s) taken to protect the expansion joint from damage during construction;
- g. Please provide any instruction or cautions from the manufacturer of the expansion joint related to the susceptibility to damage and the need to protect the expansion joint during construction;
- h. Please provide an estimate of the time and cost to replace the joint including:
 1. Cost of the replacement expansion joint;
 2. Hours and cost of engineering, construction, QC and testing personnel to replace the joint, re-hydro the blowdown line and conduct a local leak rate test of the expansion joint;
 3. Please update this estimate with actual hours and cost when available.
- i. Please provide any schedule impact related to replacement of the expansion joint.

Response:

Please see electronic Trade Secret ("TS") Attachment STF-199-2.

Contact: Jeremiah Haswell