COMMISSIONERS

TRICIA PRIDEMORE , Chairman
TIM G. ECHOLS , Vice-Chairman
FITZ JOHNSON
LAUREN "BUBBA" McDONALD
JASON SHAW

FILED
JAN 24 2023
EXECUTIVE SECRETARY
G.P.S.C.

REECE McALISTER
EXECUTIVE DIRECTOR

MICHELLE THEBERT
FACILITIES PROTECTION UNIT DIRECTOR

Georgia Public Service Commission

(404) 463-6526
(800) 282-5813

244 Washington Street, SW
Atlanta, GA 30334-5701

FAX: (404) 463-6532
psc.ga.gov

Docket No. 37024

DOCKET# 37024
DOCUMENT# 192887

AGL - Operations and Engineering
Ten Peachtree Place, NE Suite 1000
Location 1365
Atlanta, GA 30309

REF: Construction Inspection # AT22-033

☐ Certified Mail ☐ Regular Mail ☒ Email

Attention: Mr. Pedro Cherry

On July 7, 2022, a representative of the Georgia Public Service Commission Pipeline/Facilities Safety Office conducted an inspection of your gas system. The enclosed inspection report numbered AT22-033 is provided for your information and file.

In conjunction with this inspection report, Staff has recommended the following enforcement(s):

Enforcement Action:

- ☐ Notice of Probable Violation
- ☐ Notice of Probable Violation with Proposed Civil Penalty
- ☐ Notice of Amendment

Enforcement Letter:

- ☐ Warning Letter
- ☐ Letter of Concern

Enforcement Notification:

- ☐ Observed Issue
- ☒ No Violation

Please review and respond to this report in accordance with the attached Instructions for Responding to Enforcement Actions, Enforcement Letters, and Notifications Issued by the Georgia Public Service Commission. Please refer to Docket No. 37024 in your response.

Please let me know if there are any questions concerning this report at (404) 985-4271 or mthebert@psc.ga.gov. Thank you for your continuing contribution toward increased pipeline safety.

Sincerely,

Michelle Thebert

Michelle L. Thebert
Director, Office of Pipeline Safety/Facilities Protection

COMMISSIONERS

TRICIA PRIDEMORE , Chairman
TIM G. ECHOLS , Vice-Chairman
FITZ JOHNSON
LAUREN "BUBBA" McDONALD
JASON SHAW

REECE McALISTER
EXECUTIVE DIRECTOR

MICHELLE THEBERT
FACILITIES PROTECTION UNIT DIRECTOR

Georgia Public Service Commission

(404) 463-6526
(800) 282-5813

244 Washington Street, SW
Atlanta, GA 30334-5701

FAX: (404) 463-6532
psc.ga.gov

REPORT OF NATURAL GAS SAFETY

INSPECTION NO: AT22-033

OPERATOR: AGL - NW GA

INVESTIGATOR: Alan Towe

INSPECTION DATE: July 7, 2022 REPORT MAILED DATE: January 19, 2023

Any questions concerning this report may be directed to the above address or by telephoning (404) 463-6526.

1. PURPOSE OF INSPECTION

To conduct an inspection of the Operators construction project for compliance with the minimum federal standards in 49CFR Part 192.

2. CONTINUING VIOLATIONS

Violation	Description	Inspection#	Date
192.605(a)	Each operator shall prepare and follow for each pipeline, a manual of written procedures for...	AT21-005	1/5/2021

3. CLEARED VIOLATIONS

4. NEW VIOLATIONS

5. OTHER RECOMMENDATIONS/COMMENTS

On July 7, 2022, Staff reported to Floyd County to conduct an inspection of the Atlanta Gas Light Company six-inch high pressure coated steel pipeline construction project for compliance with 49CFR Part 192 of the minimum federal safety standards.

During this inspection the Operator was represented by:
Anthony Linley – Construction Inspector, Atlanta Gas Light Company
Bobby Smith – Quality Assurance Specialist, Atlanta Gas Light Company
Luis Perez – Foreman, Pride Utilities
Jose Vital– Foreman, Pride Utilities

Commission Staff was represented by Alan Towe, Lead Inspector.

At the time of this inspection the AGLC/N W Georgia Service Center had one previously existing violations. Because this Inspection was performed in the field Staff did not review this violation.

NO VIOLATIONS FOUND

During this inspection Staff found that the Operator was performing reconstruction in Floyd County. Staff reviewed the Operators procedures, materials, joining application and installation of six-inch high pressure steel main being performed by the Operators contractor Pride Utilities. Staff found that the Operator was installing approximately 150 feet of six-inch epoxy coated steel main by directional boring under the railroad to abandon existing shorted casing.

As a result of this inspection Staff noted no probable violations of the minimum federal safety standards.

Also, Staff performed O.Q. Protocol 9 field inspections on the following individuals: Mr. Luis Perez, for the following covered tasks:

1. Task #008A-ECC – Inspection and Application of Coating.
2. Task #008D – Inspection of Coating by Jeeping.

Staff found that their contractor employees' qualification records were up to date and no issues were found during the field observations.

Please review and respond to this report in accordance with the attached Instructions for Responding to Enforcement Letters Issued by the Georgia Public Service Commission.

BEFORE THE GEORGIA PUBLIC SERVICE COMMISSION
STATE OF GEORGIA

IN THE MATTER OF:	)	
	)	
No Violation Report	)	**DOCKET NO. 37024**
Atlanta Gas Light Company-NW GA	)	
Inspection AT22-033 on July 7, 2022	)	
	)	

CERTIFICATE OF SERVICE

I, the undersigned, do hereby certify that I have caused to be served a copy of the foregoing, and a copy of same was served upon all parties and persons listed below via electronic mail as indicated by an asterisk I further certify that the *Atlanta Gas Light Company* was served a hard copy of the above-stated document by U.S. Mail, certified/return receipt requested.

*Sallie Tanner, Executive Secretary
Georgia Public Service Commission
244 Washington Street, SW
Atlanta, GA 30334

* Pedro Cherry, President and CEO
Southern Company Gas
Ten Peachtree Place, NE,
Atlanta, GA 30309
ppcherry@southernco.com

*Michelle Thebert, Facilities Protection Unit Director
Georgia Public Service Commission
244 Washington Street, SW
Atlanta, GA 30334

Respectfully Submitted this 24th day of January 2023:

Cathy Nesbitt, Administrative Assistant
Georgia Public Service Commission
Facilities Protection Unit
244 Washington Street, SW
Atlanta, GA 30334