Atlanta Gas Light

Ten Peachtree Place
Atlanta, GA 30309

404 584-4000
www.southernco.com

November 13, 2023

Ms. Michelle Thebert
Director, Facility Protection Section
Georgia Public Service Commission
244 Washington Street, SW
Health Building, Suite 542H
Atlanta, GA 30334-5701

Dear Ms. Thebert:

Please find enclosed Atlanta Gas Light Company's (AGLC) two quarterly reports relating to continuing efforts to reduce the number of third-party damages to our underground facilities in Georgia.

The reports included are as follows:

- *Damage Report Summary*: July - September 2023
- *Quarterly Damage Comparison Report*: July - September 2022 compared to 2023

Report Highlights:

The third-party damage performance metrics during the 3rd quarter of 2023 are as follows:

- Damages: 928
- Locates: 218,831
- Damages /1000 Locates: 4.24

The cause of damage per 1000 locates during this quarter are as follows:

- 2.60 damages were due to the Excavator being at fault
  - 1.75 Excavator error damages were due to Damaging within the Tolerance Zone
  - 0.67 Excavator error damages were due to Excavating Without a Valid Locate Ticket
  - 0.00 Excavator error damages were due to other causes such as Failure to Preserve Marks,
  - 0.18 Excavating Outside Scope, etc.

- 0.16 damages were due to Excavator – Municipal Error
  - 0.13 Municipal error damages were due to damaging within the tolerance zone
  - 0.03 Municipal error damages were due to excavating without a valid ticket
  - 0.00 Excavating Outside Scope, etc.

- 1.15 damages were due to Locator Error
  - 0.58 Locator error damages were due to Marking Error
  - 0.51 Locator error damages were due to Failure to Mark the Facility
  - 0.06 Locator error damages were due potholing to verify locate marks

- 0.11 damages were due to Unknown Damagers

- 0.21 damages were due to AGLC or AGLC Contractor Error
    - 0.15 AGLC error damages were due to Inaccurate AGL Records
    - 0.03 AGLC error damages were due to Unlocatable Pipe
    - 0.00 AGLC error damages were due to other causes such as shallow service, late kill service order completion, etc.
    - 0.00 AGLC Contractor error damages were due to Failure to Mark the Facility or Marking Error
    - 0.03 AGLC Contractor error damages were due to damaging within the tolerance zone

As part of our continuing commitment to damage prevention, AGLC continues to utilize and improve the following processes for the overall damage prevention program. They include the following.

- **Difficult to Locate Assistance:** When locators and contractors encounter problems with locating AGLC facilities, Asset Protection Specialists and Service Centers assist with the locate efforts to ensure damage does not occur. The Company continues to incorporate the Request For Assistance Form available through its internal SharePoint Site. Continued use of the Jameson Gas Line Tracer has proven to be effective. AGLC remains committed to exploring new technology and alternative methods for locating gas facilities.

- **High Profile Locate Process:** The High Profile Locate process remains in effect. Asset Protection Specialists and ROW Inspectors advise excavators that the scope of the project could include HP or critical facilities. The Specialists and Inspectors then educate the excavators on safe digging practices when working around gas lines. This process helps to raise awareness for excavators in the field.

- **Locator Error:** AGLC continues to work with its locate contractors (USIC & Stake Center Locating) in the areas of Locator at Fault Damages and On-Time Performance. The split of “Large Project” locate requests away from regular production locate requests has allowed for a more concentrated effort to address increased demand in the Large Project arena.

- **Focus on Education and Quality Audits**: The improved root cause analysis and statistically based audit process allows Asset Protection personnel to deliver additional and targeted education and training.
    - Approximately 13,485 excavators and locators were trained on the dig law, etc. through formal and tailgate sessions from July, 1 through September 30, 2023.
    - AGL has continued contacting top damagers to schedule educational sessions. This has resulted in numerous safe digging sessions with excavators and locator training that would otherwise not have been possible.

- **Watch and Protect Program**:
    - AGLC continues to utilize the Watch and Protect program (W&P) to identify high risk tickets for all excavation work through the use of predictive analytics. AGLC deploys W&P resources to the riskiest of those sites for direct and immediate intervention. While the predictive analytics model continues to learn, AGLC continues to realize the benefits of this approach. In comparison to the 2022 Q3 Combined LP & Production damage ratio of 3.34, the 2023 Q3 Combined LP & Production damage ratio is 3.84. AGLC’s expectation is that, as the model continues to learn, the efficacy of the actionable data will improve.



Should you have questions or if I may be of further assistance, please do not hesitate to contact me. I can be contacted by telephone at my cell phone - (404) 694-3115.

Sincerely,

Alieu Lette

Alieu Lette
Manager, Asset Protection

Enclosures
CC: Commissioner Tricia Pridemore
Commissioner Tim Echols
Commissioner Lauren McDonald, Jr.
Commissioner Jason Shaw
Commissioner Fitz Johnson

Mr. Pedro Cherry
Mr. Don Carter
Mr. Jim Fletcher
Mr. Rick Lonn
Mr. Tim Brown
Mr. Blake O'Farrow
Mr. Emeka Igwilo