DISTRIBUTION PIGGING REPORT

DIVERSIFIED UTILITY SERVICES

Project Name: Bedford estates Ph 5 Date: 11-9-22

AFE: _____ WR No: _____ Job No: 22-1533

Foreman Name: [redacted] Crew No: 157

Pipe Section	Start Location (station or description)	End Location (station or description)	Pipe Material	Pipe Diameter	Pipe length
3	Spruce Way	1st Cuddy-Sac on Jasmine	PIS	2"	1441'

Label each pig with a "Unique Identifier" and include in the cell provided under each "Pig Type"

Pig Run No:	Pig Type Sequence (in order as they travel down pipe) 1st	2nd	3rd	4th	All Pigs Exited (Y/N)	Pig condition Pipe Condition	photo? (Y/N)
1	Soft	Hard			Y	Good	N
2							
3							
4							
5							

REMARKS:

[redacted] [redacted] _____ _____

Crew Foreman (print) Signature Date

_____ _____ _____

Crew Supervisor (print) Signature Date

_____ _____ _____

Coordinator (print) Signature Date

Scanned with CamScanner

DISTRIBUTION PIGGING REPORT

DIVERSIFIED UTILITY SERVICES LLC
"Safety is our goal"

Project Name: Bedford estates Date: _____

AFE: 2814342 WR No: 11044580 Job No: 22-1133

Foreman Name: [redacted] Crew No: _____

Pipe Section	Start Location (station or description)	End Location (station or description)	Pipe Material	Pipe Diameter	Pipe length
3	Spruce way	Jasmine Way.	PE	2"	286'

Pig Run No:	Pig Type Sequence (in order as they travel down pipe) 1st	2nd	3rd	4th	All Pigs Exited (Y/N)	Pig condition Pipe Condition	photo? (Y/N)
1	SOFT	Hard			Y	Good.	N
2							
3							
4							
5							

REMARKS:

[redacted] _____ _____
Crew Foreman (print) Signature Date

_____ _____ _____
Crew Supervisor (print) Signature Date

_____ _____ _____
Coordinator (print) Signature Date

Scanned with CamScanner