DISTRIBUTION PIGGING REPORT

Project Name: Bedford estates ph 5 Date: _____

AFE: 2814342 WR No: 11044580 Job No: 22-1133

Foreman Name: [redacted] Crew No: 151

Pipe Section	Start Location (station or description)	End Location (station or description)	Pipe Material	Pipe Diameter	Pipe length
	Spruce Way	Honey grape DR.	PE	2"	970'

Pig Run No:	Pig Type Sequence (in order as they travel down pipe) 1st	2nd	3rd	4th	All Pigs Exited(Y/N)	Pig condition Pipe Condition	photo? (Y/N)
1	Soft	Hard			Y	Good.	N
2							
3							
4							
5							

REMARKS:

[redacted] _____ _____

Crew Foreman (print) Signature Date

_____ _____ _____

Crew Supervisor (print) Signature Date

_____ _____ _____

Coordinator (print) Signature Date

Scanned with CamScanner

DISTRIBUTION PIGGING REPORT

DIVERSIFIED UTILITY SERVICES LLC
"Safety is our goal"

Project Name: Bedford estates Date: _____

AFE: 2814342 WR No: 11044580 Job No: 22-1133

Foreman Name: [redacted] Crew No: _____

Pipe Section	Start Location (station or description)	End Location (station or description)	Pipe Material	Pipe Diameter	Pipe length
3	Spruce Way	Jasmine Way.	PE	2"	72'

Pig Run No:	Pig Type Sequence (in order as they travel down pipe) 1st	2nd	3rd	4th	All Pigs Exited(Y/N)	Pig condition Pipe Condition	photo? (Y/N)
1	Soft	Hard			Y	Good.	N
2							
3							
4							
5							

REMARKS:

[redacted] _____ _____
Crew Foreman *(print)* Signature Date

_____ _____ _____
Crew Supervisor *(print)* Signature Date

_____ _____ _____
Coordinator *(print)* Signature Date

Scanned with CamScanner

DISTRIBUTION PIGGING REPORT

DIVERSIFIED UTILITY SERVICES LLC
"Safety is our goal"

Project Name: Bedford estates Ph 5 Date: _____

AFE: 2814342 WR No: 11044580 Job No: 22-1133

Foreman Name: [redacted] Crew No: 151

Pipe Section	Start Location (station or description)	End Location (station or description)	Pipe Material	Pipe Diameter	Pipe length
2	Spruce way	Spruce @ holly Grape.	PE	2"	625'

Pig Run No:	Pig Type Sequence (in order as they travel down pipe) 1st	2nd	3rd	4th	All Pigs Exited (Y/N)	Pig condition Pipe Condition	photo? (Y/N)
1	Soft	hard			Y	Good	N
2							
3							
4							
5							

REMARKS:

[redacted] _____ _____ _____
Crew Foreman (print) Signature Date

_____ _____ _____
Crew Supervisor (print) Signature Date

_____ _____ _____
Coordinator (print) Signature Date

Scanned with CamScanner