

NOON
MIDNIGHT
6 AM
6 PM
Bedford Estates (Persimmon Dr) PL2" x 47ft
BR B 0-150psi
DATE
Graphic Controls
4/8/2025
(A)

(A)

TEST CHART DIVERSIFIED UTILITY SERVICES, LLC.

Please fill in appropriate spaces

I.R.# Bedford Estates

JOB NAME Bedford Estates LOCATION 1770

DATE ON 4-8 TIME 11:40 am TEMP 54°

DATE OFF 4-8 TIME 1:00 pm TEMP 61°

TEST TYPE (AIR) NITROGEN WATER

FOREMAN [redacted] COORDINATOR [redacted]

SUPERVISOR [redacted] COMPLETION DATE 4-9-2026

TEST DURATION 1 HRS 20 MIN

TEST PRESSURE PSIG MINIMUM 103#

PIPE SIZES	2"		
LENGTH	47'		
MATERIAL	PL		

DISTRIBUTION PIGGING REPORT

DIVERSIFIED UTILITY SERVICES LLC

Project Name: Bedford. ESTATES Date: 4-8-25

AFE: _____ WR No: _____ Job No: 25-1605

Foreman Name: [redacted] Crew No: 141

Pipe Section	Start Location (station or description)	End Location (station or description)	Pipe Material	Pipe Diameter	Pipe length
	Driveway	Bell Hole	PLS	2"	60 Ft.

Pig Run No:	Pig Type Sequence (in order as they travel down pipe) 1st	2nd	3rd	4th	All Pigs Exited (Y/N)	Pig condition Pipe Condition	photo? (Y/N)
1	Soft	Sof	Hard.		Y	Good	yes
2							
3							
4							
5							

REMARKS:

all Pigs came out Clean and Dry

[redacted] Crew Foreman (print) [redacted] Signature 4-8-25 Date

[redacted] Crew Supervisor (print) [redacted] Signature 4-8-25 Date

[redacted] Coordinator (print) [redacted] Signature 4-8-25 Date

CamScanner